





Consumables kit for Spotters




All the essential consumables for your traditional or inverter spot welder in a kit:

- 10 stars 
- 6 bevelled caps 
- 18 round caps A type 
- 18 round caps F type 



Material of the caps: Copper Chrome Zirconium (Ø outside: 13 mm - Ø inside: 10 mm)

| Kit suitable for GYSPOT | Delivered as standard with arm |
|-------------------------|--------------------------------|
| ▪ 32 DX | RX1 – RX2 – RX3 |
| ▪ 32 DC | RC1 – RC2 – RC3 |
| ▪ 100 RX | RX1 – RX2 – RX3 |
| ▪ 100 RC | RC1 – RC2 – RC3 |
| ▪ BP LX | X1 |
| ▪ BP LC | C1 |
| ▪ BP LCX | X1 - C1 |
| ▪ Evolution PTI | C1 |

| Arm | Compatibles caps | | |
|----------------------------------|---|---|---|
| |  |  |  |
| ▪ X1-X3-X4ABC-X6-X7 (BP in X) | OK | | |
| ▪ RX1-RX2 (32D – 100R in X) | OK | | Possible |
| ▪ X2-X4-(BP in X) | | OK | |
| ▪ RX3 (32D - 100R in X) | | OK | |
| ▪ C1-C2-C3-C4-C5-C7-C8-C9RC1-RC3 | OK | | |
| ▪ RC1-RC3 (32D – 100R in C) | OK | | Possible |
| ▪ Single point (BP-100R-32D-PTI) | | | OK |

INFORMATION AND ADVICE ON CAPS

Replace the caps approximately every 200 points.

OPTIONS:



Caps Removing Wrench
Ref. 050846



Contact grease tube
Ref. 050440

Copper-based,
For perfect electrical contact



Round caps A type x 6
Ref. 049987



Caps bevelled x 6
Ref. 049994



Round caps F type x 6
Ref. 049970